

RECEIVING
INSPECTION CARD

SUPPLIER'S ADVISE NOTE NUMBER	DATE	QTY. RECD.	NEXT INSP.	QTY. INSP.	QTY. REJ.	REMARKS	DMC INSP STAMP
22848	13/1/82	87		4		Sent for Rework to T 1548	(DMC INSP STAMP)
D.M.C.	13.1.82						
Rework.	82.1.82	87	-	4	-	Accepted After Rework T.S.A.N. 1548.	(DMC INSP STAMP)
22887.	15.1.82	73	-	2	-	SENT TO Rework. T.S.A.N. 1548.	(DMC INSP STAMP)
Dmc	15.1.82						
R/W	82.1.82	73		2		Accepted after Rework	(DMC INSP STAMP)
22960	19 JAN. 1982	45		4		REMOVED WITH FILE ALL READY REWORKED 10	(DMC INSP STAMP)
22974.	20.1.82	41	-	6	-	Accepted P.T.M.I. & Visual. No Rework Recd.	(DMC INSP STAMP)
23202	25.1.82	75	-	2		ORD Stock Now to be used	(DMC INSP STAMP)
23202	25.1.82	75	-	2	-	For mid-East Cars.	(DMC INSP STAMP)
	26.1.82	95	-	2		Accepted P.T.M.I. & Visual.	(DMC INSP STAMP)
23202	26.1.82					Accepted after rework	(DMC INSP STAMP)
23253	28.1.82	59	-	2	-	Sent for rework to TSA 1548	(DMC INSP STAMP)
23248	28.1.82	76		2	-	Sent for rework T.S.A. 1548	(DMC INSP STAMP)
DMC	28/1/82						
R/w.	82.1.82	59	-	2	-	Accepted after r/w	(DMC INSP STAMP)
D.M.C.	28.1.82						
Rework.	82.1.82	76	-	4	-	Accepted After Rework. T.S.A.N. 1548.	(DMC INSP STAMP)